



# LOGIC BEACH, Inc.

*Instruments designed with the User in mind*

## SOFTWARE RELEASE NOTES

**Product:** HyperWare-II, Build 2053

**Release Date:** 8-20-2010

### FIRMWARE COMPATIBILITY:

This build is compatible with IntelliLogger firmware versions containing '19' as the second digit in the firmware version number.

Note: It is always recommended to update IntelliLogger firmware and HyperWare-II to the latest version if possible.

### BUILD SUB-COMPONENTS AND VERSIONS:

This HyperWare-II Release contains the following sub-components. Not all components are updated in each release. For reference, the version numbers of these components are provided below:

Code Component	Version	Updated?
HyperWare.exe	1.19.1.29	Not Updated
GreenWater.exe	1.19.1.17	Updated
MultiCommLib.dll	1.19.1.10	Not Updated
ILControls.dll	1.19.1.15	Not Updated
Clib.dll	1.19.1.10	Not Updated

### MODIFICATIONS CONTAINED IN THIS RELEASE:

Fixed a problem where Greenwater Web Page objects were not always being updated properly.

**LOGIC BEACH INCORPORATED**

8363 - 6F Center Drive La Mesa, CA 91942 | Tel: 619-698-3300 | Fax: 619-469-8604 | [www.logicbeach.com](http://www.logicbeach.com)